



# Heavy Machinery Safety

## Use safe practices while operating machines.

- Always wear your seat belt.
- Don't allow riders.
- Know the machine's lifting capacity.
- Stay a minimum of 10' away from overhead power lines.
- Perform a safety check of equipment and vehicles before departure. Report any maintenance concerns.
- Know the location of the fire extinguisher.
- Stay aware of pedestrian traffic.